





chronograph utility

## Functions

- ← Select COM port
- ← Open / Close COM port
- ← Read data from a .txt file
- ← Save data to a .txt file
- ← Clear data
- ← Projectile weight ( grams or grains )
- ☒ ← Chart (checkbox) – Automatic scrolling of the SHOTS axis
- ☐ ← Chart (blank checkbox) – Dynamic scaling (data compression)
- ☒ ← Units: Metric / Imperial units
- ☒ ← Auto & Auto50 – Dynamic scaling of the VELOCITY axis

- ← Jump to the start of the SHOTS axis
- ← Jump to the end of the SHOTS axis

- ← Zoom in / Zoom out on the SHOTS axis



## Starting the Program

- Before use, please read the terms of the free license: License.txt
- Connect the device to the computer using a USB or USB-COM cable
- Switch on the chronograph and run the program ( EXE file)
- Select the new COM port and press the OPEN button
- Data will be sent after each shot or when reading from the device's memory
- Program compatible with Windows 7 SP1, Windows 8, Windows 10, Windows 11
- Run as administrator or disable antivirus software (optional)